

US EPA ARCHIVE DOCUMENT

## DECONTAMINATION/STAGING SITE ASSESSMENT

Facility Name :	Biloxi Decon Area (Yates Construction)	Facility Location ID:	BD01
Assessment Date :	9/9/2010	Incident Name :	BP Spill
Physical Location :	215 Michael Industrial Blvd		
City, State :	Biloxi , MS	County :	Harrison

### ASSESSMENT INFORMATION

General Site Information and Observations			
1. All waste stored in lined rolloff boxes?	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> N/A
2. Rolloff boxes covered after filled (or end of day)?	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> N/A
3. Any evidence of oily waste or oily waste waters?	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> N/A
4. If yes, was it adequately addressed?			
5. How many samples were collected?			
<b>Additional Comments :</b> Met with Hamp Sterling (Yates) and Paul Musick (Yates). The decon area was not active at the time of this visit. No incident derived oily waste was present at the decon area during the visit. No samples were collected. No concerns regarding waste management practices were noted during the visit.			